














5-in-1 Multi Sander







5 ב 1 רב תכליתיים מכונת ליטוש



WX820 WX820.1 WX820.9






A5**A6****A7****A8****B1**









D1WX820
WX820.1**D2**

WX820.1

D3

WX820.1

E**F****G**



GENERAL POWER TOOL SAFETY WARNINGS



WARNING: Read all safety warnings, instructions, illustrations and specifications provided with this power tool.

Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

1) Work area safety

- a) **Keep work area clean and well lit.** Cluttered or dark areas invite accidents.
- b) **Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.** Power tools create sparks which may ignite the dust or fumes.
- c) **Keep children and bystanders away while operating a power tool.** Distractions can cause you to lose control.

2) Electrical safety

- a) **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- b) **Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- c) **Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- d) **Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts.** Damaged or entangled cords increase the risk of electric shock.
- e) **When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.
- f) **If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply.** Use of an RCD reduces the risk of electric shock.

3) Personal safety

- a) **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of**

drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.

- b) **Use personal protective equipment. Always wear eye protection.** Protective equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.
 - c) **Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool.** Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
 - d) **Remove any adjusting key or wrench before turning the power tool on.** A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
 - e) **Do not overreach. Keep proper footing and balance at all times.** This enables better control of the power tool in unexpected situations.
 - f) **Dress properly. Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts.** Loose clothes, jewellery or long hair can be caught in moving parts.
 - g) **If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.** Use of dust collection can reduce dust-related hazards.
 - h) **Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles.** A careless action can cause severe injury within a fraction of a second.
- ## 4) Power tool use and care
- a) **Do not force the power tool. Use the correct power tool for your application.** The correct power tool will do the job better and safer at the rate for which it was designed.
 - b) **Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.**
 - c) **Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools.** Such preventive safety measures reduce the risk of starting the power tool accidentally.
 - d) **Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.** Power tools are dangerous in the hands of untrained users.
 - e) **Maintain power tools and accessories. Check for misalignment or binding of**

moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.

- f) Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- g) Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed.** Use of the power tool for operations different from those intended could result in a hazardous situation.
- h) Keep handles and grasping surfaces dry, clean and free from oil and grease.** Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.
- 5) Battery tool use and care**
- a) Recharge only with the charger specified by the manufacturer.** A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- b) Use power tools only with specifically designated battery packs.** Use of any other battery packs may create a risk of injury and fire.
- c) When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another.** Shorting the battery terminals together may cause burns or a fire.
- d) Under abusive conditions, liquid may be ejected from the battery; avoid contact. If contact accidentally occurs, flush with water.** If liquid contacts eyes, additionally seek medical help. Liquid ejected from the battery may cause irritation or burns.
- e) Do not use a battery pack or tool that is damaged or modified.** Damaged or modified batteries may exhibit unpredictable behaviour resulting in fire, explosion or risk of injury.
- f) Do not expose a battery pack or tool to fire or excessive temperature.** Exposure to fire or temperature above 130 °C may cause explosion.
- g) Follow all charging instructions and do not charge the battery pack or tool outside the temperature range specified in the instructions.** Charging improperly or at temperatures outside the specified range may damage the battery and increase the risk of fire.
- 6) Service**
- a) Have your power tool serviced by a qualified repair person using only identical replacement parts.** This will ensure that the safety of the power tool is maintained.
- b) Never service damaged battery packs.**

Service of battery packs should only be performed by the manufacturer or authorized service providers.

SAFETY WARNINGS FOR BATTERY PACK

- a) Do not dismantle, open or shred cells or battery pack.**
- b) Do not short-circuit a battery pack. Do not store battery packs haphazardly in a box or drawer where they may short-circuit each other or be short-circuited by conductive materials.** When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another. Shorting the battery terminals together may cause burns or a fire.
- c) Do not expose battery pack to heat or fire. Avoid storage in direct sunlight.**
- d) Do not subject battery pack to mechanical shock.**
- e) In the event of battery leaking, do not allow the liquid to come into contact with the skin or eyes. If contact has been made, wash the affected area with copious amounts of water and seek medical advice.**
- f) Seek medical advice immediately if a cell or battery pack has been swallowed.**
- g) Keep battery pack clean and dry.**
- h) Wipe the battery pack terminals with a clean dry cloth if they become dirty.**
- i) Battery pack needs to be charged before use. Always refer to this instruction and use the correct charging procedure.**
- j) Do not maintain battery pack on charge when not in use.**
- k) After extended periods of storage, it may be necessary to charge and discharge the battery pack several times to obtain maximum performance.**
- l) Battery pack gives its best performance when it is operated at normal room temperature (20 °C ± 5 °C).**
- m) When disposing of battery packs, keep battery packs of different electrochemical systems separate from each other.**
- n) Recharge only with the charger specified by WORX. Do not use any charger other than that specifically provided for use with the equipment.** A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- o) Do not use any battery pack which is not designed for use with the equipment.**
- p) Keep battery pack out of the reach of children.**
- q) Retain the original product literature for future reference.**
- r) Remove the battery from the equipment**

- when not in use.
- s) **Dispose of properly.**
 - t) **Do not mix cells of different manufacture, capacity, size or type within a device.**
 - u) **Do not remove battery pack from its original packaging until required for use.**
 - v) **Observe the plus (+) and minus (-) marks on the battery and ensure correct use.**

SYMBOLS

	To reduce the risk of injury, user must read instruction manual
	Warning
	Wear ear protection
	Wear eye protection
	Wear dust mask
	Make sure the battery is removed prior to changing accessories.
	Prohibit hands enter before moving parts stop
	Lock
	Unlock
	Wear protective gloves
	Do not burn

	Do not expose to rain or water
 Li-Ion	Do not dispose of batteries. Return exhausted batteries to your local collection or recycling point.
	Hot! Do not touch

COMPONENT LIST

1. HYPERLOCK™ ACCESSORY CLAMPING LEVER
2. ON/OFF SWITCH
3. HANDLE
4. HYPERLOCK™ RELEASE BUTTON
5. BATTERY PACK RELEASE BUTTON*
6. BATTERY PACK*
7. PLATE INTERFACE
8. VARIABLE SPEED DIAL
9. DUST BAG
10. FINISHING PLATE
11. RANDOM ORBIT PLATE
12. DETAIL PLATE
13. FINGER PLATE
14. CONTOUR PLATE
15. PAPER PUNCH

* Not all the accessories illustrated or described are included in standard delivery.

TECHNICAL DATA

	WX820	WX820.1	WX820.9
Charger Voltage	100-240V ~ 50/60Hz		
Voltage	20 V $\overline{\text{---}}$ Max**		
No load speed	4000-10000 /min		
Orbital diameter	Random orbit-2.5mm, Finish-1.8mm, Detail-1.8mm		
Speed settings	1-6		
Machine weight	2.0kg	1.5kg	

** Voltage measured without workload. Initial battery voltage reaches maximum of 20 volts. Nominal voltage is 18 volts.

ACCESSORIES

	WX820	WX820.1	WX820.9
Battery pack (WA3551.1)	1	1	/
Battery pack (WA3553)	/	1	/
Charger (WA3860)	1	1	/
Finishing plate	1	1	1
Random Orbit plate	1	1	1
Detail plate	1	1	1
Finger plate	1	1	1
Contour plate	1	1	1
Dust bag	1	1	1
Paper punch	1	1	1
185*95mm Finishing sanding paper	3	3	3
125mm Random orbit H&L sanding paper	3	3	3
140*90mm Detail H&L sanding paper	3	3	3

76*30mm Finger H&L sanding paper	3	3	3
100*50mm Contour H&L sanding paper	3	3	3

We recommend that you purchase your accessories listed in the above list from the same store that sold you the tool. Refer to the accessory packaging for further details. Store personnel can assist you and offer advice.

OPERATING INSTRUCTIONS



NOTE: Before using the tool, read the instruction book carefully.

INTENDED USE:

This machine is intended for dry sanding of wood, plastic, filler and coated surfaces. The sander is not to be used for plaster or spackle.

ASSEMBLY AND OPERATION

ACTION	FIGURE
ASSEMBLY	
Fitting & Replacing the Sanding Plate NOTE: Read and understand the instructions before assembling or changing sanding plates. NOTE: Open the Hyperlock lever completely when attaching or removing a sanding plate. NOTE: When assembling the finishing plate/detail plate, first check the assembling direction.  WARNING! The sanding plate must be attached before starting the sander.  WARNING! Avoid pinching hands and fingers when using the hyperlock™.  WARNING! Do not touch the bottom fan after use to avoid high-temperature burns.	See Fig. A1-A8
Fitting the Sanding Paper	See Fig. B1-B6
Attaching the Dust Bag CAUTION:  To prevent the possibility of dust or a foreign body being thrown into your face or eyes, never attempt to use your sander without the dust bag properly installed.	See Fig. C

Charging the Battery Pack			See Fig. D1,D2,D3
Installing the Battery Pack			See Fig. E
OPERATION			
Switching On/Off			See Fig. F
Using the Variable Speed Dial (Speed settings 1-6) -The Variable Speed Dial can be used to set the optimum speed according to the sanding plate used and the respective application.			See Fig. G
Application	Sanding paper	Speed	
Sanding down varnishes	180...400	3-6	
Sanding paint	40...120	4-6	
Touching up paintwork	120...240	1-5	
Sanding wood	60...240	1-6	
Machining veneer	180...240	3-5	
Derusting metal	40...120	4-6	
Sanding metal and steel	120...240	4-6	
Sanding curved surface	60...240	1-6	
Removing the Battery Pack			See Fig. H
Emptying the Dust Bag -For more efficient operation, empty dusts bag every 5-10 mins.			See Fig. I1-I2

WORKING HINTS FOR YOUR MULTISANDER

If your power tool becomes too hot, especially when used at low speed, set the speed to maximum and run it with no load for 2-3 minutes to cool the motor. Avoid prolonged usage at very low speed. Always use sand paper that is suitable for the material you want to sand. Always ensure the work-piece is firmly held or clamped to prevent movement. Any movement of the material may affect the quality of the sanding finish.

Start your sander before sanding and turn it off only after you stop sanding. For the best results, sandwood in the direction of the grain.

Do not start sanding without having the sandpaper fitted.

Do not allow the sandpaper to wear away it will damage the base-plate. The guarantee does not cover base-plate wear and tear.

Use coarse grit paper to sand rough surfaces, medium grit for smooth surfaces and fine grit for the final surfaces. If necessary, first make a test run on scrap material.

Use only good quality sandpaper.

The sandpaper controls the sanding efficiency, not the amount of force you apply to the tool. Excessive force will reduce the sanding efficiency and cause motor overload. Replacing the sandpaper regularly will maintain optimum sanding efficiency.

MAINTENANCE

Remove the battery pack from the tool before carrying out any adjustment, servicing or maintenance.

There are no user serviceable parts in your power tool. Never use water or chemical cleaners to clean your power tool. Wipe clean with a dry cloth. Always store your power tool in a dry place. Keep the motor ventilation slots clean. Keep all working controls free of dust. Occasionally you may see sparks through the ventilation slots. This is normal and will not damage your power tool.

FOR BATTERY TOOLS

The ambient temperature range for the use and storage of tool and battery is 0°C-45°C.

The recommended ambient temperature range for the charging system during charging is 0°C-40°C.

ENVIRONMENTAL PROTECTION



Disposal

The machine, its accessories and packaging materials should be sorted for environmentally friendly recycling. The plastic components are labeled for categorized recycling.

מתאים לסוללות

כלים וסוללות טווח טמפרטורות אחסון של 0°C - 45°C .
הטמפרטורות המומלצות לטמפרטורות הטעינה במהלך הטעינה
הן 0°C - 40°C .

הגנה סביבתית

סילוק

יש למיין א מכשיר זה, את אביזריו ואת חומרי האריזה
לצורך מחזור ידידותי לסביבה.
הרכיבים עשויים מפלסטיק מתויגים צורך מחזור ממין.



שם החברה: סמיקום לקסיס בע"מ
כתובת: א"ת מערבי קדימה ת.ד. 9090 אבן יהודה
טלפון: 09-7611222
www.semicom.co.il

הוראות הפעלה

הערה: קראו בעיון רב את חוברת ההוראות לפני השימוש בכלי.

שימוש מיועד

מכונה זו מיועדת לטיפול ישב של משטחי עץ, פלסטיק, גומחות (פילרים) ומשטחים צבועים. אין להשתמש במכונה הטיפול לטיח

הרכבה והפעלה

אזור	פעולה
הרכבה	
ראה אזור A1-A8	להתקין ולהחליף את צלחת מלטש הערה: קראו והבן את ההוראות לפני הרכבה או החלפה של לוח הצלילה. הערה: בעת התקנה או הסרה של לוח השיוף, פתחו את ידית Hyperlock במלואה. הערה: בעת הרכבת לוח הגמר / לוחית הסימון, בדוק תחילה את כיוון ההרכבה. ⚠ אזהרה! צלחת הצלילה חייבת להיות מחוברת למיד לפני תחילת הסנדר. ⚠ אזהרה! בעת שימוש hyperlock™, למנוע צביטה הידניים והאצבעות. ⚠ אזהרה! אל תיגע במאורר התחתון לאחר השימוש כדי למנוע כוויתן טמפרטורה גבוהות.
ראה אזור B1-B6	מתאים לנייר זכוכית
ראה אזור C	⚠ חיסור שקית איסוף האבק ⚠ אזהרה: לעולם אל תנסו להשתמש במלטשת מבלי ששקית איסוף האבק אינה מחוברת כראוי, למניעת אפשרות פגיעת אבק וגופים זרים בעיניים ובפנים.
ראה אזור D1, D2, D3	טען את מארז הסוללה
ראה אזור E	התקן את מארז הסוללה
הפעלה	
ראה אזור F	הפעלה / כיבוי
ראה אזור D	השתמש בחיוג מהיר משתנה הגדרת מהירות (1-6) - חיוג מהיר משתנה ניתן להשתמש כדי להגדיר את המהירות האופטימלית בהתאם צלחת מלטש בשימוש והיישום המתאים.

יישום	נייר מלטש	מהירות
פוליש לכה	180---400	3-6
צבע מלטש	40---120	4-6
גם בצבע	120---240	1-5
עץ מלוטש	60---240	1-6
לוח עיבוד	180---240	3-5
מתכת דסקלינג	40---120	4-6
ליטוש מתכת ופלדה	120---240	4-6
משטח מלוטש	60---240	1-6
הסר את מארז הסוללה		
ראה אזור H	ריקון שקית איסוף האבק - רוקנו את שקית איסוף האבק כל 5-10 דקות להשגת תוצאות העיבוד הטובות ביותר.	
ראה אזור I1-I2		

טיפים לעבודה עם המלטשת

הניחו לכלי העבודה לפעול במהירות מרבית במשך 2-3 דקות ללא עומס, על מנת לאפשר למנוע להתקרר כשהכלי חם, בעיקר לאחר שימוש במהירות נמוכה. הימנעו משימוש ממושך במהירות נמוכה. השתמשו תמיד בנייר הלטש המתאים לסוג החומר לעיבוד. ודאו תמיד שהפריט לעיבוד מוחזק או מהודק היטב לשולחן העבודה למניעת תזוזות.

כל תזוזה של הפריט לעיבוד עלולה לפגוע באיכות הגימור. הפעילו את המלטשת לפני פעולת הליטוש וכבו אותה רק בגמר הליטוש. להשגת תוצאות מיטביות בליטוש משטחי עץ, לטשו תמיד בכיוון הגריירים.

אל תפעילו את המלטשת ללא נייר לטש.

אל תשתמשו בנייר לטש בלוי, למניעת נזק לפלדת הבסיס.

האחריות אינה מכסה בלאי של בסיס הפלטה.

השתמשו בנייר לטש גס עבור משטחים מחוספסים, בנייר לטש בינוני עבור משטחים חלקים ובנייר לטש עדין לגימור הסופי. עשו ניסיונות על גרסאות, במידת הצורך.

השתמשו בניירות לטש איכותיים.

יעילות הליטוש מושפעת מנייר הלטש ולא ממידת הכוח שמפ-עילים על הכלי. הפעלת כוח רב מדי פוגעת בביצועי המלטשת ומעמיסה על המנוע. החלפה תכופה של נייר הלטש שומרת על ליטוש יעיל.

תחזוקה

יש לנתק את התקע מהשקע לפני ביצוע כונוון, שירות או תחזוקה.

המכשיר החשמלי שלך אינו צורך סכנה או תחזוקה נוספות. אין במכשיר החשמלי שלך חלקים ברי שירות המשתמש. לעולם אין להשתמש במים או בכימיקלים לניקוי לצורך ניקוי המכשיר החשמלי. יש לנגב במטלית יבשה. יש לאחסן תמיד במקום יבש. יש לשמור על פתחי האוורור נקיים. יש לשמור על בקורות המכשיר כשהן נקיות מאבק. מדי פעם ניתן לראות ניצוצות דרך חריצי האוורור. זהו מצב תקין והוא לא יגרום נזק למכשיר.

מפרט טכני

WX820.9	WX820.1	WX820	
100-240V~50/60Hz			מתח מטען
20V~עד**			מתח
4000-10000סל"ד			מהירות סיבוב
מסלול אקראי-2.5 מ"מ, גימור-1.8 מ"מ, פרט-1.8 מ"מ			קוטר סיבוב
1-6			הגדרות מהירות
2.0 ק"ג		1.5 ק"ג	משקל נקי

** מתח נמדד ללא עומס. מתח הסוללה הראשוני מגיע למקסימום 20V. המתח הנומינלי הוא 18V

תכולת האריזה

WX820.9	WX820.1	WX820	
/	1	1	1(WA3551)הסוללה
/	1	/	1(WA3553)הסוללה
/	1	1	1(WA3860)מטען
1	1	1	גימור הלוח
1	1	1	לוח רנדומלי אקראי
1	1	1	לוח פירוט
1	1	1	אצבע
1	1	1	לוח קונטור
1	1	1	שקית איסוף אבק
1	1	1	אגרופי נייר
3	3	3	מ"מ 95mm * 185 גימור נייר מלטש
3	3	3	מ"מ מסלול 125mm * 125 מלטש H & L אקראי נייר
3	3	3	לפר- 90mm * 140 מלטש נייר H & L טים
3	3	3	מ"מ 30 * 76 נייר מלטש H & L אצבע
3	3	3	קונטור 50mm * 100 מלטש נייר H & L

מומלץ שתרכשו את האביזרים מאותה חנות בה רכשתם את הכלי. עיינו בהוראות על גבי אריזת האביזר למידע נוסף. צוות החנות יכול לסייע ולייעץ לכם.

אל תחשפו לגשם או למים	
אל תשליכו את הסוללות ביחד עם האשפה הביתית. הביאו אותן למתקן איסוף מתאים לצורך מחזור.	 Li-Ion
חם! אל תיגע	 Li-Ion

חלקי המכשיר

1. Hyperlock™ מוט מהדק אביזר
2. מתג הפעלה / כיבוי
3. ידית
4. לחצן שחרור Hyperlock™
5. לחצן שחרור ערכת הסוללות*
6. מארז סוללות*
7. ממשק לוח
8. חיוג מהיר משתנה
9. שקית אשפה
10. גימור הלוח
11. לוח רנדומלי אקראי
12. לוח פירוט
13. אצבע
14. לוח קונטור
15. נייר ניקוב

*חלק מהאביזרים המוצגים בחוברת זו או המתוארים בה הם

- ו. אין לחשוף מארז סוללות או כלי לאש או לטמפרטורה חריגה. חשיפה לאש או לטמפרטורה מעל 130°C עלולה לגרום התפוצצות.
- ז. יש להקפיד על כל הוראות הטעינה. אין לטעון את מארז הסוללות או הכלי בטמפרטורה החורגת מהטווח המצוין בהוראות. טעינה שגויה או טעינה מחוץ לטווח הטמפרטורה המצוין עלולה להזיק לסוללה ולהגביר את הסיכון לשריפה.

מלים

	העל המשתמש לקרוא את חוברת ההוראות, להפחתת הסיכון בפגיעה
	אזהרה
	לבשו מגני אוזניים
	לבשו מגני עיניים
	לבשו מסכת אבק
	וודא שהסוללה הורחקה טרם החלפת החלקים
	אין להזין את הידיים לפני עצירה חלקים נעים
	נעל
	ביטול נעילה
	לבש כפפות הגנה
	אל תשרפו

6) שירות

- א. על השירות לכלי העבודה החשמלי להינתן ע"י טכנאי מוסמך המשתמש בחלקי חילוף מקוריים. דבר זה יבטיח שבטיחות כלי העבודה החשמלי תישמר.
- ב. אין לנסות לתקן מארזי סוללות פגומים. רק היצרן או ספקי שירות מוסמכים רשאים לטפל במארזי סוללות.

הוראות בטיחות לסוללה

- א. אל תפרקו, אל תפתחו ואל תגרסו את תאי הסוללה או הסוללה.
- ב. אל תקצרו את הסוללה. אל תאחסנו סוללות בחופזה בארגז או במגירה בהם ין יכולות לקצר אחת את השנייה או להתקצר ע"י חומרים מוליכים.
- בזמן השימוש היזהרו שהסוללה לא תבוא במגע עם חפצי מתכת כגון סיכות נייר, מטבעות, מפתחות, מסמרים, ברגים או חפצים דומים העלולים לגרום לחיבור בין שני השקעים. קצר כפול במגעם עלול לגרום לשריפה או לכוויות.
- ג. אל תחשפו את הסוללות לחום או לאש. הימנעו מאחסון באור שמש ישיר.
- ד. אל תחשפו את הסוללות לחבטות.
- ה. אל תאפשרו לנוזל האלקטרוליט לבוא במגע עם העור או העיניים במקרה של דליפה. שטפו את האזור הנגוע בכמויות מים גדולות במקרה של מגע ופנו לקבלת סיוע רפואי.
- ו. פנו מיד לקבלת סיוע רפואי במקרה של בליעה.
- ז. שמרו על סוללה נקייה ויבשה. נגבו את מגעי הסוללה במטלית נקייה ויבשה במקרה של לכלוך.
- ח. יש לטעון את הסוללה לפני השימוש. עיינו תמיד בהוראות השימוש וההפעלה ופעלו בהתאם להוראות הטעינה. אל תטענו את הסוללה כשאינה בשימוש.
- ט. ייתכן ויהיה צורך במספר מחזורי טעינה ופריקה לאחר תקן פות אחסון ארוכות ללא שימוש, להשגת ביצועים מיטביים.
- י. הסוללה פועלת באופן מיטבי בטמפרטורת חדר רגילה (5°C ± 20°C).
- יא. טענו באמצעות המטען המסופק בלבד. שימוש במטען שאינו מתאים לסוג הסוללה עלול לגרום דליקה.
- יב. הרחיקו את הסוללה כשאינה בשימוש מחפצי מתכת אחרים כגון אטבי נייר, מטבעות, מפתחות, מסמרים, ברגים וחפצי מתכת קטנים אחרים העלולים לקצר את מגעי הסוללה. קיצור מגעי הסוללה עלול לגרום כוויה או דליקה.
- יג. נזל אלקטרוליט עלול לדלוף מהסוללה כשמנקבים אותה; הימנעו ממגע. שטפו את האזור הנגוע בכמויות מים גדולות במקרה של מגע ופנו לקבלת סיוע רפואי במקרה של מגע עם העיניים. מגע עם נזל האלקטרוליט עלול לגרום גירוי או כוויה.
- יד. נקו את מגעי הסוללה ואת מגעי הכלי לפני התקנת הסוללה.
- טו. אל תשתמשו בסוללות שאינן מיועדות לשימוש עם כלי העבודה החשמלי.
- טז. הרחיקו את הסוללה מהישג ידם של ילדים.
- יז. שמרו את החוברת במקום בטוח, לעיון בעתיד.
- יח. הסירו את הסוללה מהכלי כשאינו בשימוש.
- יט. השליכו את הסוללה באופן ידידותי לסביבה.
- א. אין לערבב סוללות של ייצור, קיבולת, גודל או סוג שונים בתוך ההתקן.

הוראות בטיחות כלליות לכלי עבודה חשמליים



אזהרה: יש לקרוא את כל אזהרות הבטיחות, ההוראות, האזהרות והמפרטים המצורפים לכלי עבודה זה. למניעת התחשמלות, דליקה וא/או פציעה. התחשמלות, דליקה וא/או פציעה.

שמרו את החוברת במקום בטוח, לעיון בעתיד. המונח "כלי עבודה חשמלי" באזהרות מתייחס לכלי עבודה מופעל חשמל (חוטי) או כלי עבודה מופעל סוללה (אלחוטי).

1. התלבשו בהתאם. אל תלבוש בגדים רפויים או תכשיטים. יש להקפיד על מרחק בין השיער והבגדים לבין חלקים נעים. בגדים רפויים, תכשיטים או שיער ארוך עלולים להיתפס בחלקים נעים.
2. כשמסופקים מתאמים לחיבור שואב אבק יש לוודא שהם מתואמים היטב ומשתמשים בהם כראוי. שימוש בשואב אבק מקטין את הסיכונים הקשורים לאבק.
3. יש להימנע ממצב שבו היכרות עקב שימוש תכופ בכלים ות-ביל ליטונות ולהתעלמות מעקרונות הבטיחות של הכלים. רשלנות עלולה לגרום לפציעה חמורה תוך שבריר שנייה.

4 שימוש ותחזוקה

- א. אל תפעילו כוח על כלי העבודה החשמלי. השתמשו בכלי העבודה החשמלי המתאים למשימה. כלי העבודה החשמלי המתאים יעשה את העבודה בצורה בטוחה וטובה יותר בקצב העבודה עבורו הוא מיועד.
- ב. אל השתמשו בכלי העבודה החשמלי אם המתג אינו מפעיל או מכבה אותו. כל כלי עבודה חשמלי שאינו ניתן לשליטה באמצעות המתג הוא מסוכן ויש לתקנו.
- ג. נזקו את התקע ממקור המזלח ו/או הוציאו את הסוללה מכלי העבודה החשמלי לפני ביצוע כיוונים כלשהם, החלפת אביזרים או אחסון. נקטו אמצעי בטיחות כאלה מקטינה את הסיכון להפעלה בשוגג של כלי העבודה החשמלי.
- ד. אחסנו כלי עבודה חשמליים שאינם בשימוש רחוק מהישג ידם של ילדים ואל תאפשרו לאנשים שאינם בקיאים בהפ-עלת כלי העבודה החשמלי או בהוראות אלה להפעיל אותו. כל כלי עבודה חשמליים מהווים סכנה בידיהם של משתמשים לא מנוסים.
- ה. שמרו על כלי עבודה חשמליים תקינים. בדקו אחר חלקים נעים עקומים או מכופפים, חלקים שבורים וכל נזאי אחר העלול להשפיע על פועלת כלי העבודה החשמלי. דאגו לתיקון כלי עבודה חשמלי עגום לפני השימוש בו. תאונות רבות נגרמות בשל שימוש בכלי עבודה חשמליים פגומים.
- ו. שמרו על כלי חיתוך חדים ונקיים. כלי חיתוך מתוחזקים כראוי עם קצוות חיתוך חדים נטיים פחות להתכופף וקלים יותר לשליטה.
- ז. השתמשו בכלי העבודה החשמלי, באביזרים בביטויים וכד' בהתאם להוראות אלה, תוך התחשבות בתנאי העבודה ובמבנה העבודה לביצוע. שימוש בכלי העבודה החשמלי לכל מטרה אחרת מלבד לזו הוא מיועד עלול להיות מסוכן.
- ח. יש לשמור על הידיות ועל משטחי האחיזה יבשים, נקיים וולא שמן או גריז. ידיות ומשטחי אחיזה חלקלקים מונעים עבודה בטוחה ושלטה בכלי במצבים בלתי-צפויים.

5 שימוש בכלי עבודה מופעל סוללה ותחזוקת

- א. טענו באמצעות המטען המסופק ע"י היצרן בלבד. מטען המ-תאים לסוג סוללה אחד עלול לגרום סכנת דליקה כשמשתמשים בו לטעינת סוללה מסוג אחר.
- ב. השתמשו בכלי העבודה עם סוללות המיועדות לו בלבד.
- ג. שימוש בסוללות אחרות עלול לגרום סכנת פציעה או דליקה. הרחיקו את הסוללה, כשאינה בשימוש, מחפצים מתכתיים אחרים כגון אטבי נייר, מטבעות, מפתחות, מסמרים, ברגים או חפצים מתכתיים קטנים אחרים, העלולים ליצור מגע בין שני קוטבי הסוללה. קיצור קוטבי הסוללה יחדיו עלול לגרום כוויות לדליקה.
- ד. בתנאי שימוש קיצוניים נוזל הסוללה עלול לדלוף ממנה; הימנעו ממגע. טשפו מיד במים במקרה של מגע בשוגג. בנוסף, פנו לקבלת סיוע רפואי במקרה של מגע עם העיניים. הנוזל הדלף מהסוללה עלול לגרום גירוי או כוויות.
- ה. אין להשתמש במארג סוללות או בכלי שנפגעו או שעבר שינויים. סוללות אשר נפגמו או עברו שלטים עלולות לגרום להתנהגות בלתי-צפויה אשר תוביל לשריפה, להתפוצצות או לסכנת פציעה.

1 בטיחות באזור העבודה

- א. שמרו על אזור עבודה נקי ומאור היטב. אזורים מלוכלכים או חסויים מזמזמים ותאונות.
- ב. אל תפעילו כלי עבודה חשמליים בסביבות נפיצות, כגון בקר-בות נזלים דליקים, גזים או אבק. כלי עבודה חשמליים יוצרים ניצוצות העלולים להצית חלקיקי אבק או אדים.
- ג. הרחיקו ילדים ואנשים אחרים בעת הפעלת כלי עבודה חשמלי. הסחות דעת עלולות לגרום לכם לאבד שליטה.

2 בטיחות חשמלית

- א. על תקעי כלי העבודה החשמליים להתאים לשקעים החשמליים. לעולם אל תשנו את התקע בכל צורה שהיא. אל השתמשו במתאמים תקינים כלשהם לחיבור כלי עבודה חשמליים מוארקים. תקעים תקינים ושקעים חשמליים תואמים מקטינים את הסיכון להתחשמלות.
- ב. הימנעו ממגע עם משטחים מוארקים, כגון צינורות, דריאטורים, תנורי בישול ומקררים. הסיכון להתחשמלות גדל כשגופכם מוארק.
- ג. אל תחשפו את כלי העבודה החשמליים לגשם או ללחות. חדירת מים לכלי העבודה החשמלי מגדילה את הסיכון להתח-שמלות.
- ד. אל תפעילו כוח על כבל הזינה. לעולם אל תשתמשו בכבל לנשיאת הכלי או לניתוקו מהשקע החשמלי. הרחיקו את הכבל מחום, משמן, מקצוות חדים או מחלקים נעים. כבלים פגומים או מפותלים מגדילים את הסיכון להתחשמלות.
- ה. השתמשו בכבל מאריך המתאים לשימוש מחוץ למבנה בעת הפעלת כלי עבודה חשמלי מחוץ למבנה. שימוש בכבל המ-תאים לשימוש מחוץ למבנה מקטין את הסיכון להתחשמלות.
- ו. השתמשו במפסק פחת כשלא ניתן להימנע מהפעלת כלי עבודה חשמלי בסביבה לחה. השימוש במפסק פחת מקטין את הסיכון להתחשמלות.

3 בטיחות אישית

- א. היו ערים, שימו לב למה שאתם עושים ונהגו בהיגיון בעת הפעלת כלי עבודה חשמלי. אל תשתמשו בכלי עבודה חשמלי כשאתם עייפים או תחת השפעת כדורים, אלכוהול או תרופות. רגע של חוסר תשומת לב בעת הפעלת כלי עבודה חשמליים עלול לגרום פציעה חמורה.
- ב. השתמשו בציוד מגן אישי. לבשו תמיד משקפי מגן. שימוש בציוד מגן אישי כגון מסכת אבק, נעלי בטיחות מוגנות החלקה, קסדה או מגני אוזניים מקטין את הסיכון לפציעה.
- ג. מנעו הפעלה בלתי צפויה. ודאו שהמתג במצב כבוי לפני חיבור הכלי למקור מתח ו/או סוללה, הרמת הכלי או נשיאתו. נשיאת כלי עבודה חשמליים כשהאצבע על המתג או חיבורם לרקע כשהמתג במצב פעולה מזמזמים ותאונות.
- ד. הסירו מפתחות כווננו או מפתחות ברגים לפני הפעלת כלי העבודה החשמלי. מפתח ברגים או מפתח כווננו המחובר חלק מסתובב של כלי העבודה החשמלי עלול לגרום פציעה.
- ה. אל תתמחות על מנת להגיע למקומות מרוחקים. שמרו תמיד על עמידה יציבה. דבר זה מאפשר שליטה טובה יותר בכלי העבודה החשמלי במצבים בלתי צפויים.



www.worx.com

Copyright © 2019, Positec. All Rights Reserved.
AR01438100